Form: rprocess

Thursday, 31/07/2008 2:44:20 PM Julie Lecoca **Process Sheet** : CU-DARQ01 Dart Helicopters Services : HEAD REST ASSEMBLY CENTER **Drawing Name** Customer : 40817 Job Number **Estimate Number** : 10861 : D412724041 Part Number P.O. Number **Drawing Number** . N/A : 31/07/2008 S.O. No. : This Issue : N/A Project Number Prsht Rev. : NC : N/A : SMALL /MED FAB : 30/07/2008 Type **Drawing Revision** First Issue : 40168 **Material** Previous Run **Due Date** : 06/08/2008 Written By Checked & Approved By New Issue KJ/JLM : Est Rev:A 04.09.08 Comment Additional Product Job Number: Description: Machine Or Operation: Seq. #: DOCUMENT CONTROL DC 1.0 Comment: DOCUMENT CONTROL If D412-724-041 is a W/O on it's own, Photocopy bluefile and create labels per PPP D412-724-041 CHG001 PACKAGING RESOURCE #1 PACKAGING 1 2.0 Comment: PACKAGING RESOURCE #1 Pick Packing Kit Head Rest 3.0 D3303041 Comment: Qty.: 1.0000 Each(s)/Unit 12.0000 Each(s) Total: Pick: Packing Kit **Qty Part Number** Description Batch 08/08/20/12 1 D3303-041 Head Rest D3304041 4.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 12.0000 Each(s) Pick: Packing Kit **Qty Part Number** Description Batch 40188 x2 D3304-041 **Tube Assembly** 08/08/74 RR AN52510R6 Screw Comment: Qty.: Total: 48.0000 Each(s) 4.0000 Each(s)/Unit Pick: Packing Kit **Qty Part Number** Description Batch M15943 x6 M161203x2

Thursday, 31/07/2008 2:44:20 PM Julie Lecocq

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: HEAD REST ASSEMBLY CENTER

Job Number: 40817

Part Number: D412724041

Description:

Job Number:



Seq. #:

Machine Or Operation:

AN525-10R6 Screw

6.0


QC4

INSPECT 100% KITS FOR COMPLETENESS



Comment: INSPECT

100% KITS FOR COMPLETENESS



7.0

PACKAGING 1

PACKAGING RESOURCE #1




Comment: PACKAGING RESOURCE #1

Identify and pack for shipping as per PPP D412-724-041

Location:

PPP Rev:

FINAL INSPECTION/W/O RELEASE



8.0

QC21





Comment: FINAL INSPECTION/W/O RELEASE

Job Completion

